

AMC (American Motors)

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
AMX								
	Rear Axle							
	1968 - 1970	AMC	AMC 20	29	12	V8	92-0120-2900	92-0120-2920
	1968 - 1971	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
	1978	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
Concord								
	Rear Axle							
	1978 - 1979	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
	1978 - 1979	AMC	AMC 20	29	12	V8	92-0120-2900	92-0120-2920
Eagle								
	Front Axle (see notice at end of page 2)							
	1980 - 1988	DANA	Model 30	27	10		92-0430-2700	
	Rear Axle							
	1980 - 1988	DANA	Model 35	27	10	All	92-0435-2700	92-0435-2720
Full size								
	Rear Axle							
	1965 - 1978	AMC	AMC 20	29	12	V8	92-0120-2900	92-0120-2920
	1962 - 1978	DANA	Model 35	27	10		92-0435-2700	92-0435-2720
Gremlin								
	Rear Axle							
	1970 - 1978	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
	1970 - 1978	AMC	AMC 20	29	12	V8	92-0120-2900	92-0120-2920
Hornet								
	Rear Axle							
	1970 - 1977	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
	1970 - 1977	AMC	AMC 20	29	12	V8	92-0120-2900	92-0120-2920
Javelin								
	Rear Axle							
	1971 - 1974	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
Marlin								
	Rear Axle							
	1965 - 1967	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
Pacer								
	Rear Axle							
	1975 - 1979	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
Spirit								
	Rear Axle							
	1979	DANA	Model 35	27	10	4 & 6 Cyl.	92-0435-2700	92-0435-2720
Hummer								
	Front Axle (see notice at end of page 2)							
	1991 - 2000	AMC	AMC 20	29	12	Requires new differential case	92-0120-2900	92-0120-2920
	Rear Axle							
	1991 - 2000	AMC	AMC 20	29	12	Requires new differential case	92-0120-2900	92-0120-2920

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

BUICK

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
All Passenger Models (Unless listed separately below)								
Rear Axle								
	1996	GM	8.5" rg	28	10		92-0785-2805	
	1977 - 1985	GM	7.5" rg	26	10		92-0775-2605	
	1971 - 1983	GM	8.875" rg	30	12		92-0788-3005	
	1973 - 1976	GM	8.875" rg	31		Station Wagon		
	1965 - 1970	GM	8.2" rg	28	10			
Apollo								
Rear Axle								
	1973 - 1975	GM	8.5" rg	28	10		92-0785-2805	
Century								
Rear Axle								
	1978 - 1981	GM	7.5" rg	26	10		92-0775-2605	
	1977	GM	8.875" rg	30	12		92-0788-3005	
	1973 - 1977	GM	8.5" rg	28	10		92-0785-2805	
	1973 - 1976	GM	8.875" rg	31		Station Wagon		
Regal								
Rear Axle								
	1978 - 1987	GM	7.5" rg	26	10		92-0775-2605	
	1973 - 1987	GM	8.5" rg	28	10		92-0785-2805	
Riviera								
Rear Axle								
	1977 - 1978	GM	8.5" rg	28	10		92-0785-2805	
	1977 - 1978	GM	8.875" rg	30	12		92-0788-3005	
	1975 - 1976	GM	8.875" rg	31		Station Wagon		
	1971 - 1975	GM	9.375" rg					
	1965 - 1970	GM	8.2" rg	28	10		Spring 2001	
Skyhawk								
Rear Axle								
	1975 - 1980	GM	7.5" rg	26	10		92-0775-2605	
	1976 - 1977	GM	6.5" rg					
Skylark								
Rear Axle								
	1978 - 1987	GM	7.5" rg	26	10		92-0775-2605	
	1973 - 1987	GM	8.5" rg	28	10		92-0785-2805	
Special								
Rear Axle								
	1971 - 1972	GM	8.5" rg	28	10		92-0785-2805	
	1970	GM	8.875" rg	30	12		92-0788-3005	
	1964 - 1970	GM	8.2" rg	28	10		Spring 2001	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

CADILLAC

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
All Passenger Models (Unless listed separately below)								
Rear Axle								
	1991 - 1996	GM	8.5" rg	28	10		92-0785-2805	
	1991 - 1996	GM	9.5" rg	33	14		92-0795-3305	
	1988 - 1990	GM	7.625" rg	26	10	w/o Towing	92-0776-2605	
	1987 - 1990	GM	8.5" rg	28	10	Towing/Armored opt.	92-0785-2805	
	1985 - 1987	GM	7.5" rg	26	10	w/o Towing	92-0775-2605	
	1984	GM	8.5" rg	28	10	Round cover	92-0785-2805	
	1982 - 1984	GM	7.5" rg	26	10	DeVille/Fleetwood Brougham	92-0775-2605	
	1977 - 1984	GM	8.875" rg	30	12	Comercial Chassis	92-0788-3005	
	1977 - 1983	GM	8.875" rg	30	12	Deville cutout cover	92-0788-3005	
	1977 - 1982	GM	8.875" rg	30	12	Fleetwood Brougham	92-0788-3005	
	1970 - 1976	GM						
Seville								
Rear Axle								
	1976 - 1979	GM	8.5" rg	28	10		92-0785-2805	
Escalade								
Front Axle (see notice at bottom of page)								
	1999 - 2000	GM	8.2" rg	28		IFS w/6 Lug		
	1999 - 2000	GM	9.2" rg	33		IFS w/turbo diesel	92-0792-3301	
Rear Axle								
	1999 - 2000	GM	8.5" rg	30	10		92-0785-3005	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

CHEVROLET

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Gov Lock
All Passenger Models (Unless listed separately below)								
Rear Axle								
	1994 - 1996	GM	7.625" rg	28	10	V6	92-0776-2805	92-0776-2885
	1971 - 1996	GM	8.5" rg	28	10	V8	92-0785-2805	
	1975 - 1993	GM	7.5" rg	26	10	V6	92-0775-2605	
	1977 - 1983	GM	8.875" rg	30	12	V8-396 Eng.or larger	92-0788-3005	
	1971 - 1976	GM	8.875" rg	31	12	Station Wagon		
	1965 - 1970	GM	8.2" rg	28	10		Spring 2001	
	1965 - 1970	GM	8.875" rg	30	12	V8-396 Eng.or larger	92-0788-3005	
Camaro								
Rear Axle								
	1993 - 2000	ZEXEL				Z28/Y87		
	1990 - 2000	GM	7.625" rg	28	10	V6	92-0776-2805	92-0776-2885
	1987 - 1989	GM	7.75" rg		9	V8 w/o Z87- L/S ONLY		
	1987 - 1989	GM	7.625" rg	26	10	V6	92-0776-2605	
	1985 - 1986	GM	7.625" rg	26	10	All	92-0776-2605	
	1982 - 1984	GM	7.5" rg	26	10	4 cyl/V6	92-0775-2605	
	1971 - 1981	GM	8.5" rg	28	10	All	92-0785-2805	
	1967 - 1970	GM	8.875" rg	30	12	V8	92-0788-3005	
	1967 - 1970	GM	8.2" rg	28	10	6 cyl	Spring 2001	
Caprice								
Rear Axle								
	1973 - 1975	GM	8.875" rg	31	12	Police & SW		
	1971 - 1975	GM	8.5" rg	28	10		92-0785-2805	
	1966 - 1970	GM	8.875" rg	30	12		92-0788-3005	
	1966 - 1970	GM	8.2" rg	28	10		Spring 2001	
Chevelle								
Rear Axle								
	1973 - 1977	GM	8.5" rg	28	10		92-0785-2805	
	1973 - 1976	GM	8.875" rg	31	12	Police & SW		
	1964 - 1972	GM	8.2" rg	28	10		Spring 2001	
	1964 - 1972	GM	8.875" rg	30	12	SS	92-0788-3005	
Chevy II								
Rear Axle								
	1962 - 1967	GM	8.875" rg	30	12	w/396 or larger eng.	92-0788-3005	
	1962 - 1967	GM	8.2" rg	28	10		Spring 2001	
Corvette								
Rear Axle								
	1980 - 2000	DANA	Model 44	30				
Impala								
Rear Axle								
	1994 - 1996	GM	8.5" rg	30	10	SS	92-0785-3005	
	1973 - 1975	GM	8.875" rg	31	12	Police & SW		
	1971 - 1975	GM	8.5" rg	28	10		92-0785-2805	
	1960 - 1970	GM	8.2" rg	28	10		Spring 2001	
	1960 - 1970	GM	8.875" rg	30	12	SS	92-0788-3005	

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Gov Lock
Malibu								
Rear Axle								
	1978 - 1987	GM	7.5" rg	26	10		92-0775-2605	
Monte Carlo								
Rear Axle								
	1973 - 1975	GM	8.5" rg	28	10		92-0785-2805	
	1970 - 1972	GM	8.875" rg	30	12		92-0788-3005	
	1970 - 1972	GM	8.2" rg	28	10		Spring 2001	
Monza								
Rear Axle								
	1975 - 1980	GM	7.5" rg	26	10		92-0775-2605	
	1976 - 1977	GM	6.5" rg					
Nova								
Rear Axle								
	1964 - 1971	GM	8.875" rg	30	12	w/396 or larger eng.	92-0788-3005	
	1972 - 1975	GM	8.5" rg	28	10		92-0785-2805	
	1964 - 1971	GM	8.2" rg	28	10		Spring 2001	
Vega								
Rear Axle								
	1976 - 1977	GM	6.5" rg					
	1975 - 1977	GM	7.5" rg	26	10		92-0775-2605	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

CHEVROLET

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	GM Gov Lock	Dana Trac Lock
Astro									
Front Axle (see notice at end of page 4)									
	1990 - 2000	GM	7.2" rg	26					
Rear Axle									
	1990 - 2000	GM	7.625" rg	28	10	4WD	92-0776-2805	92-0776-2885	
	1985 - 1989	GM	7.5" rg	26	10	JM4	92-0775-2605		
Blazer (S-10)									
Front Axle (see notice at end of page 4)									
	1983 - 2000	GM	7.2" rg	26					
Rear Axle									
	1995 - 2000	GM	8.5" rg	30	10	Z71 OPT/RPO G87	92-0785-3005		
	1988 - 2000	GM	7.625" rg	28	10	4WD V6	92-0776-2805	92-0776-2885	
	1983 - 1995	GM	7.5" rg	26	10	2WD All & 4WD 4 CYL	92-0775-2605		
Blazer (Full size)									
Front Axle (see notice at end of page 4)									
	1994	GM	9.2" rg	33		IFS w/turbo diesel	92-0792-3301		
	1992 - 1994	GM	8.2" rg	28		IFS w/6 lug			
	1989 - 1991	GM	8.5" rg	30	10	Beam Axle	92-0785-3005		
	1979 - 1988	GM	8.5" rg	28	10	Beam Axle	92-0785-2805		
	1969 - 1980	DANA	Model 44	30	10	See cover ID chart	92-0444-3000	92-0444-3020	
Rear Axle									
	1992 - 1994	GM	9.5" rg	33	14	All w/14 bolt cover	92-0795-3305		
	1989 - 1994	GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
	1982 - 1988	GM	8.5" rg	28	10		92-0785-2805		
	1969 - 1981	GM	8.875" rg	30	12		92-0788-3005		
El Camino									
Rear Axle									
	1976 - 1987	GM	7.5" rg	26	10		92-0775-2605		
	1973 - 1975	GM	8.5" rg	28	10		92-0785-2805		
	1964 - 1972	GM	8.2" rg	28	10		Spring 2001		
	1964 - 1972	GM	8.875" rg	30	12		92-0788-3005		
LUV									
Rear Axle									
	1979 - 1982	ISUZU		17					
Pick-Up (S-10)									
Front Axle (see notice at end of page 4)									
	1983 - 2000	GM	7.2" rg	26					
Rear Axle									
	1995 - 2000	GM	8.5" rg	30	10	Z71 OPT/RPO G87	92-0785-3005		
	1996 - 2000	GM	7.625" rg	28	10	All	92-0776-2805		
	1988 - 1995	GM	7.625" rg	28	10	4WD V6	92-0776-2805	92-0776-2885	
	1983 - 1995	GM	7.5" rg	26	10	2WD All & 4WD 4 CYL	92-0775-2605		

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	GM Gov Lock	Dana Trac Lock
Pick-Up (1/2-ton)									
Front Axle (see notice at end of page 4)									
1988 - 2000		GM	8.2" rg	28		IFS 6 Lug			
1978 - 1984		GM	8.5" rg	28	10	See cover ID chart	92-0785-2805		
1963 - 1980		DANA	Model 44	30	10	See cover ID chart	92-0444-3000		92-0444-3020
Rear Axle									
1988 - 2000		GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
1988 - 2000		GM	9.5" rg	33	14	All w/14 bolt cover	92-0795-3305		
1978 - 1988		GM	8.5" rg	28	10	See cover ID chart	92-0785-2805		
1969 - 1981		GM	8.875" rg	30	12	All w/12 bolt cover	92-0788-3005		
1969 - 1977		DANA	Model 44	30	10	See cover ID chart	92-0444-3000		92-0444-3020
1968 - 1972		DANA	Model 44	30	10		92-0444-3000		92-0444-3020
Pick-Up (3/4-ton)									
Front Axle (see notice at end of page 4)									
1989 - 2000		GM	9.2" rg	33		IFS w/8 lug	92-0792-3301		
1988 - 2000		GM	8.2" rg	28		IFS w/6 lug			
1989 - 1991		GM	8.5" rg	30	10	Beam Axle	92-0785-3005		
1978 - 1988		GM	8.5" rg	28	10	VIN R-or-V Only	92-0785-2805		
1968 - 1980		DANA	Model 44	30		See cover ID chart	92-0444-3000		92-0444-3020
Rear Axle									
1973 - 2000		GM	9.5" rg	33	14	Semi-floating axle	92-0795-3305		
1973 - 2000		GM	10.5" rg	30	14	FF Axle	92-0705-3000		
1991		GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
1975 - 1977		DANA	Model 60	35	10	See cover ID chart	92-0460-3500		92-0460-3520
1965 - 1974		DANA	Model 60	30	10	Semi-floating axle	92-0460-3000		92-0460-3020
Pick-Up (1-ton)									
Front Axle (see notice at end of page 4)									
1988 - 2000		GM	9.2" rg	33		IFS VIN C/K	92-0792-3301		
1977 - 1991		DANA	Model 60	35	10	VIN R-or-V	92-0460-3500		92-0460-3520
Rear Axle									
1992 - 2000		DANA	Model 80	37	10	HD opt			
1989 - 2000		GM	9.5" rg	33	14	Canada,SF Axle	92-0795-3305		
1973 - 2000		GM	10.5" rg	30	14	w/14 bolt cover	92-0705-3000		
1990 - 1991		ROCKWELL	12" rg			HD opt			
1973 - 1991		DANA	Model 70	35	10	All w/10 bolt cover	Spring 2001		
Silverado									
Front Axle (see notice at end of page 4)									
1999 - 2000									
Rear Axle									
1999 - 2000		GM	8.6" rg	30	10		92-0786-3005		

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	GM Gov Lock	Dana Trac Lock
Suburban (1/2-ton)									
Front Axle (see notice at end of page 4)									
1994 - 2000	GM	9.2" rg	33			IFS w/turbo diesel	92-0792-3301		
1992 - 2000	GM	8.2" rg	28			IFS w/o turbo diesel			
1990 - 1991	GM	8.5" rg	30	10		Beam axle	92-0785-3005		
1977 - 1989	GM	8.5" rg	28	10			92-0785-2805		
1965 - 1980	DANA	Model 44	30	10			92-0444-3000		92-0444-3020
1965 - 1968	DANA	Model 60	35	10		10 Series HD Only	92-0460-3500		92-0460-3520
Rear Axle									
2000	GM	8.6" rg	30	10			92-0786-3005		
1992 - 1999	GM	9.5" rg	33	14		All w/14 bolt cover	92-0795-3305		
1989 - 1999	GM	8.5" rg	30	10		All w/10 bolt cover	92-0785-3005		
1978 - 1988	GM	8.5" rg	28	10		All w/10 bolt cover	92-0785-2805		
1965 - 1981	GM	8.875" rg	30	12		All w/12 bolt cover	92-0788-3005		
1965 - 1972	DANA	Model 60	30	10			92-0460-3005		92-0460-3025
1965 - 1968	DANA	Model 44	30	10			92-0444-3000		92-0444-3020
Suburban (3/4-ton)									
Front Axle (see notice at end of page 4)									
1992 - 2000	GM	8.2" rg	28			IFS w/6 lug			
1992 - 2000	GM	9.2" rg	33			IFS w/8 lug	92-0792-3301		
1989 - 1991	GM	8.5" rg	30	10		Beam axle	92-0785-3005		
1978 - 1988	GM	8.5" rg	28	10		Beam axle	92-0785-2805		
1963 - 1980	DANA	Model 44	30	10		See cover ID chart	92-0444-3000		92-0444-3020
Rear Axle									
2000	GM	8.6" rg	30	10			92-0786-3005		
1981 - 1999	GM	9.5" rg	33	14		F Axle w/14 bolt cover	92-0795-3305		
1973 - 1999	GM	10.5" rg	30	14		F Axle w/14 bolt cover	92-0705-3000		
1989 - 1991	GM	8.5" rg	30	10		All w/10 bolt cover	92-0785-3005		
1977 - 1988	GM	8.5" rg	28	10		All w/10 bolt cover	92-0785-2805		
1969 - 1980	DANA	Model 44	30	10		See cover ID chart	92-0444-3000		92-0444-3020
1968 - 1980	DANA	Model 60	30	10		See cover ID chart	92-0460-3000		92-0460-3020
Tahoe									
Front Axle (see notice at end of page 4)									
1994 - 2000	GM	9.2" rg	33			IFS w/turbo diesel	92-0792-3301		
1992 - 2000	GM	8.2" rg	28			IFS w/6 Lug			
Rear Axle									
1992 - 2000	GM	8.5" rg	30	10			92-0785-3005		
Vans (1/2-ton)									
Rear Axle									
1989 - 2000	GM	8.5" rg	30	10		All	92-0785-3005		
1979 - 1988	GM	8.5" rg	28	10		All	92-0785-2805		
1965 - 1981	GM	8.875" rg	30	12		All w/12 bolt cover	92-0788-3005		
1964 - 1971	GM	8.2" rg	28	10		All w/10 bolt cover	Spring 2001		

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	GM Gov Lock	Dana Trac Lock
Vans (3/4-ton)									
Rear Axle									
	1996 - 2000	GM	9.5" rg	33	14	F Axle, w/14 bolt cover	92-0795-3305		
	1996 - 1998	GM	10.5" rg	30	14	F Axle, w/14 bolt cover	92-0705-3000		
	1989 - 1996	GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
	1979 - 1988	GM	8.5" rg	28	10	All w/10 bolt cover	92-0785-2805		
	1965 - 1981	GM	8.875" rg	30	12	All w/12 bolt cover	92-0788-3005		
Vans (1-ton)									
Rear Axle									
	1983 - 2000	GM	9.5" rg	33	14	F Axle, w/14 bolt cover	92-0795-3305		
	1973 - 1998	GM	10.5" rg	30	14	F Axle, w/14 bolt cover	92-0705-3000		
	1975 - 1991	DANA	Model 70	35	10	DRW 7500 gvw	Spring 2001		
	1974 - 1991	DANA	Model 60	35	10	DRW 6200 gvw	92-0460-3500		92-0460-3520

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

CHRYSLER

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
All Passenger Models (Unless listed separately below)								
Rear Axle								
1982 - 1989	CHRYSLER	7.25" rg	25	10	Sq. Cover			
1972 - 1989	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2725	
1974 - 1981	CHRYSLER	9.25" rg	31	12		92-0392-3105	92-0392-3125	
1957 - 1973	CHRYSLER	8.75" rg	30	10				
1967	CHRYSLER	9.25" rg	31	12		92-0392-3105	92-0392-3125	
Cordoba								
Rear Axle								
1980 - 1983	CHRYSLER	7.25" rg	25	10				
1975 - 1983	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2725	
1975 - 1979	CHRYSLER	9.25" rg	31	12		92-0392-3105	92-0392-3125	
Imperial								
Rear Axle								
1981 - 1983	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2725	
1974 - 1975	CHRYSLER	9.25" rg	31	12		92-0392-3105	92-0392-3125	
1957 - 1973	CHRYSLER	8.75" rg	30	10				
LeBaron								
Rear Axle								
1977 - 1981	CHRYSLER	7.25" rg	25	9				
1977 - 1981	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2725	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

DODGE

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
All Passenger Models (Unless listed separately below)								
Rear Axle								
	1973 - 1981	CHRYSLER	9.25" rg	31	12		92-0392-3105	92-0392-3125
	1969 - 1981	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2725
	1962 - 1974	CHRYSLER	8.75" rg	30	10			
	1966 - 1971	CHRYSLER	7.25" rg	25	9	6 Cyl		
	1966 - 1970	DANA	Model 60	30	10	RT/SuperBee/V8-426/440	92-0460-3000	92-0460-3020
	1968	CHRYSLER	9.25" rg	31	12	Polaris/Monaco	92-0392-3105	92-0392-3125
	1962 - 1965	CHRYSLER	8.25" rg	27	10	6 Cyl	92-0382-2705	92-0382-2725
Aspen								
Rear Axle								
	1976 - 1980	CHRYSLER	7.25" rg	25	9			
	1976 - 1980	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2725
Challenger								
Rear Axle								
	1970 - 1974	CHRYSLER	8.75" rg	30	10	All w/Removable carrier		
	1970 - 1971	DANA	Model 60	30	10	V8-426/440	92-0460-3000	92-0460-3020
	1970 - 1971	CHRYSLER	7.25" rg	25	9			
Charger								
Rear Axle								
	1974 - 1978	CHRYSLER	9.25" rg	31	12		92-0392-3105	92-0392-3125
	1969 - 1978	CHRYSLER	8.25" rg	27	10	V8-318/400	92-0382-2705	92-0382-2725
	1966 - 1974	CHRYSLER	8.75" rg	30	10	All w/Removable carrier		
	1966 - 1972	DANA	Model 60	30	10	V8-426/440	92-0460-3000	92-0460-3020
	1968 - 1970	CHRYSLER	7.25" rg	25	9			
Dart								
Rear Axle								
	1973 - 1976	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2725
	1963 - 1976	CHRYSLER	7.25" rg	25	9	66-72 N/R Carrier		
	1966 - 1972	CHRYSLER	8.75" rg	30	10			
	1966 - 1970	CHRYSLER	8.75" rg	30	10	All w/Removable carrier		
Diplomat								
Rear Axle								
	1977 - 1989	CHRYSLER	7.25" rg	25	9			
	1977 - 1989	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2725
Magnum								
Rear Axle								
	1979	CHRYSLER	8.25" rg	27	10	V8-318	92-0382-2705	92-0382-2725
	1979	CHRYSLER	9.25" rg	31	12	V8-360	92-0392-3105	92-0392-3125
Marada								
Rear Axle								
	1980 - 1983	CHRYSLER	8.25" rg	27	10	V8	92-0382-2705	92-0382-2725
	1980 - 1983	CHRYSLER	7.25" rg	25	10	6 Cyl		

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Viper								
Rear Axle								
	1992 - 2000	DANA	Model 44	30				

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

DODGE

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	Chrysler SureGrip	Dana Trac Lock
Dakota									
Front Axle (see notice at end of page 3)									
	1997 - 2000	DANA	Model 35	27	10		92-0435-2701		
Rear Axle									
	1997 - 2000	CHRYSLER	8.25" rg	29	10	L/S std.	92-0382-2905		
	1987 - 1998	CHRYSLER	7.25" rg	25	10	Octagon cover			
	1987 - 1996	CHRYSLER	8.25" rg	27	10	und cover/L/S std. 94	92-0382-2705	92-0382-2745	92-0382-2725
Durango									
Front Axle (see notice at end of page 3)									
	1998 - 2000	DANA	Model 35	27	10		92-0435-2701		
Rear Axle									
	1998 - 2000	CHRYSLER	8.25" rg	29	10	V6	92-0382-2905		
	1998 - 2000	CHRYSLER	9.25" rg	31	12	V8	92-0392-3105		92-0392-3125
Pick-Up (1/2-ton)									
Front Axle (see notice at end of page 3)									
	1969 - 2000	DANA	Model 44	30	10		92-0444-3000		92-0444-3020
	1967 - 1968	DANA	Model 44	19	10		92-0444-1900		
Rear Axle									
	1995 - 2000	CHRYSLER	9.25" rg	31	12		92-0392-3105		92-0392-3125
	1981 - 1994	CHRYSLER	9.25" rg	31	12		92-0392-3105	92-0392-3145	
	1971 - 1993	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2745	
	1967 - 1974	CHRYSLER	8.75" rg	30	10	w/Removable carrier			
Pick-Up (3/4-ton)									
Front Axle (see notice at end of page 3)									
	1981 - 2000	DANA	Model 44	30	10		92-0444-3000		92-0444-3020
	1975 - 2000	DANA	Model 60	30	10	"x20" Snow Command	92-0460-3500		92-0460-3020
	1989 - 1993	DANA	Model 70	32	10	"x27" Snow Command	Spring 2001		
	1971 - 1974	DANA	Model 70	35	10		Spring 2001		
	1967 - 1968	DANA	Model 44	19	10	std.	92-0444-1900		
Rear Axle									
	1994 - 2000	DANA	Model 70	32	10	F Axle, V10&Dies, Au	Spring 2001		
	1994 - 2000	DANA	Model 80	37	10	FF Axle, V10 & Diesel			
	1983 - 2000	DANA	Model 60	30	10	F Axle, V8, Man Tran	92-0460-3000		92-0460-3020
	1995 - 2000	CHRYSLER	9.25" rg	31	12	iF Axle, V8, Auto Tran	92-0392-3105		92-0392-3125
	1981 - 1994	CHRYSLER	9.25" rg	31	12	iF Axle, V8, Auto Tran	92-0392-3105	92-0392-3145	
Pick-Up (1-ton & 1 1/2-ton)									
Front Axle (see notice at end of page 3)									
	1975 - 2000	DANA	Model 60	30	10		92-0460-3500		92-0460-3020
	1971 - 1974	DANA	Model 70	32	10	"x27" Snow Command	Spring 2001		
Rear Axle									
	1994 - 2000	DANA	Model 80	35	10				
	1981 - 1993	DANA	Model 60	30	10	6200 gvw	92-0460-3000		92-0460-3020
	1977 - 1993	DANA	Model 70	32	10	7500 gvw	Spring 2001		
	1971 - 1974	DANA	Model 70	32	10		Spring 2001		

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	Chrysler SureGrip	Dana Trac Lock
Ramcharger									
Front Axle (see notice at end of page 3)									
	1974 - 1993	DANA	Model 44	30	10		92-0444-3000		92-0444-3020
Rear Axle									
	1974 - 1993	CHRYSLER	9.25" rg	31	12		92-0392-3105	92-0392-3145	
Van 100									
Rear Axle									
	1974 - 1980	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
	1971 - 1980	CHRYSLER	8.25" rg	27	10	All w/10 bolt cover	92-0382-2705	92-0382-2745	
	1964 - 1974	CHRYSLER	8.75" rg	30	10	∥ w/Removable carrier			
Van 150									
Rear Axle									
	1981 - 1994	CHRYSLER	8.25" rg	27	10	All w/10 bolt cover	92-0382-2705	92-0382-2745	
	1984	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
	1982	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
Van 200									
Rear Axle									
	1974 - 1980	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
	1971 - 1980	CHRYSLER	8.25" rg	27	10	All w/10 bolt cover	92-0382-2705	92-0382-2745	
	1971 - 1974	CHRYSLER	8.75" rg	30	10	∥ w/Removable carrier			
Van 250									
Rear Axle									
	1992 - 1994	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
	1984	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
	1981 - 1984	CHRYSLER	8.25" rg	27	10	All w/10 bolt cover	92-0382-2705	92-0382-2745	
	1982	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
Van 300									
Rear Axle									
	1971 - 1980	DANA	Model 60	35	10	All	92-0460-3500		92-0460-3520
Van 350									
Rear Axle									
	1984 - 1994	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
	1981 - 1994	DANA	Model 60	35	10	All w/10 bolt cover	92-0460-3500		92-0460-3520
Van 1500									
Rear Axle									
	1997 - 2000	CHRYSLER	8.25" rg	29	10	All w/10 bolt cover	92-0382-2905		
	1995 - 1996	CHRYSLER	8.25" rg	27	10	All w/10 bolt cover	92-0382-2705	92-0382-2745	
Van 2500									
Rear Axle									
	1997 - 2000	CHRYSLER	8.25" rg	29	10	All w/10 bolt cover	92-0382-2905		
	1995 - 2000	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	
	1995 - 1996	CHRYSLER	8.25" rg	27	10	All w/10 bolt cover	92-0382-2705	92-0382-2745	
Van 3500									
Rear Axle									
	1995 - 2000	DANA	Model 60	30	10	All w/10 bolt cover	92-0460-3000		92-0460-3020
	1995 - 2000	CHRYSLER	9.25" rg	31	12	All w/12 bolt cover	92-0392-3105	92-0392-3145	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

FORD

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Fairlane								
Rear Axle								
	1962 - 1970	FORD	8" rg	28	10	302 or smaller eng.	92-0680-2800	
	1962 - 1970	FORD	9" rg	28	10	V8-351W/390/428/289 Spcl	92-0690-2800	
	1962 - 1968	FORD	7.25" rg			N/R Carrier		
Fairmont								
Rear Axle								
	1978 - 1983	FORD	7.5" rg	28	10			
	1979 - 1982	FORD	6.75" rg		8	4 Cyl.		
Granada								
Rear Axle								
	1981 - 1982	FORD	7.5" rg	28	10			
	1975 - 1980	FORD	9" rg	28	10		92-0690-2800	
	1975 - 1980	FORD	8" rg	28	10		92-0680-2800	
	1975 - 1976	FORD	8.75" rg	28	10		92-0690-2800	
LTD								
Rear Axle								
	1983 - 1986	FORD	7.5" rg	28	10			
LTD II								
Rear Axle								
	1977 - 1979	FORD	9" rg	28	10		92-0690-2800	
Maverick								
Rear Axle								
	1970 - 1977	FORD	8" rg	28	10		92-0680-2800	
	1971	FORD	7.25" rg			N/R Carrier		
Mustang								
Rear Axle								
	1999 - 2000	FORD	8.8" rg	31	10	Cobra	92-0688-3107	92-0688-3127
	1986 - 2000	FORD	8.8" rg	28	10	All V8 Exc. 99-00 Cobra	92-0688-2807	92-0688-2827
	1979 - 2000	FORD	7.5" rg	28	10	All V6		
	1986 - 1998	FORD	8.8" rg	31	10	GT, after market axle	92-0688-3107	92-0688-3127
	1986	FORD	8.8" rg	28	10	GT	92-0688-2807	92-0688-2827
	1979 - 1982	FORD	6.75" rg		8	4 Cyl		
	1964 - 1978	FORD	8" rg	28	10	V8 289/302	92-0680-2800	
	1965 - 1973	FORD	9" rg	31	10	after market axle	92-0690-3100	
	1965 - 1973	FORD	9" rg	28	10	351W/390/427/428/289 spec	92-0690-2800	
Pinto								
Rear Axle								
	1978 - 1980	FORD	6.75" rg		8	4 Cyl		
	1975 - 1980	FORD	8" rg	28	10	6 Cyl	92-0680-2800	
Thunderbird								
Rear Axle								
	1987 - 1989	FORD	8.8" rg	28	10	GT,V8,V6 Turbo	92-0688-2807	92-0688-2827
	1980 - 1997	FORD	7.5" rg	28	10	exc. Turbo, V8		
	1957 - 1979	FORD	9" rg	28	10		92-0690-2800	
	1957 - 1979	FORD	9" rg	31	10	after market axle	92-0690-3100	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

FORD

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Aerostar								
Front Axle (see notice at end of page 4)								
	1990 - 1997	DANA	Model 28	23	10			
Rear Axle								
	1990 - 1997	FORD	8.8" rg	31	10	4.0/4.9 V6	92-0688-3108	92-0688-3128
	1986 - 1997	FORD	7.5" rg	28	10	3.0/4cyl Fill plug in Housing		
	1986 - 1990	DANA	Model 30	27	10	3.0/4cyl Fill plug in Cover	92-0430-2700	
Bronco II								
Front Axle (see notice at end of page 4)								
	1984 - 1991	DANA	Model 28	23	12			
Rear Axle								
	1984 - 1991	FORD	7.5" rg	28	10			
Bronco (Full size)								
Front Axle (see notice at end of page 4)								
	1994 - 1996	DANA	Model 44	30	10	IFS	92-0444-3001	
	1971 - 1993	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1987 - 1996	FORD	8.8" rg	31	10		92-0688-3108	92-0688-3128
	1983 - 1986	FORD	8.8" rg	31	10		92-0688-3107	92-0688-3127
	1976 - 1986	FORD	9" rg	31	10		92-0690-3100	
	1966 - 1976	FORD	9" rg	28	10		92-0690-2800	
	1966 - 1970	DANA	Model 30	27	10		92-0430-2700	
Excursion								
Rear Axle								
	2000	FORD	10.5" rg	35	10	See cover ID chart	92-0605-3500	92-0605-3520
Expedition								
Front Axle (see notice at end of page 4)								
	1997 - 2000	DANA	Model 44	30	10		92-0444-3001	
Rear Axle								
	1997 - 2000	FORD	8.8" rg	31	10	4.6 eng	92-0688-3108	92-0688-3128
	1997 - 2000	FORD	9.75" rg	34	10	5.4 eng		
Explorer								
Front Axle (see notice at end of page 4)								
	1995 - 2000	DANA	Model 35	27	10	IFS	92-0435-2702	
	1991 - 1994	DANA	Model 28	23	12			
Rear Axle								
	1991 - 2000	FORD	8.8" rg	31	10	See cover ID chart	92-0688-3108	92-0688-3128

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Pick-Up (F100 & F150)								
Front Axle (see notice at end of page 4)								
	1994 - 2000	DANA	Model 44	30		IFS	92-0444-3001	
	1967 - 1993	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
	1957 - 1966	DANA	Model 44	19	10		92-0444-1900	
Rear Axle								
	1998 - 2000	FORD	9.75" rg	34	10	5.4		
	1987 - 2000	FORD	8.8" rg	31	10	4.2/4.6 manual transmission	92-0688-3108	92-0688-3128
	1983 - 1986	FORD	8.8" rg	31	10		92-0688-3107	92-0688-3127
	1976 - 1986	FORD	9" rg	31	10		92-0690-3100	
	1959 - 1986	FORD	9" rg	35	10	w/spec hi-perf 35 spl axles	92-0690-3500	
	1977 - 1979	DANA	Model 44	30	10	See cover ID chart	92-0444-3000	92-0444-3020
	1959 - 1977	FORD	9" rg	28	10		92-0690-2800	
Pick-Up (F250)								
Front Axle (see notice at end of page 4)								
	1997 - 2000	DANA	Model 44	30	10	IFS under 8500 gvw	92-0444-3001	
	1997 - 2000	DANA	Model 50	30		IFS over 8500 gvw		
	1985 - 1996	DANA	Model 44	30	10	Beam axle under 8500 gvw	92-0444-3000	92-0444-3020
	1975 - 1996	DANA	Model 60	35	10	See cover ID chart 4500 Axle	92-0460-3500	92-0460-3520
	1980 - 1990	DANA	Model 50	30	10	Beam axle over 8500 gvw		
	1969 - 1973	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1996 - 2000	FORD	9.75" rg	34	10	See cover ID chart		
	1999 - 2000	FORD	10.5" rg	35	12	See cover ID chart (3 pinion)	92-0605-3500	92-0605-3520
	1985 - 1998	FORD	10.25" rg	35	12	See cover ID chart (2 pinion)		
	1995 - 1996	DANA	Model 60	32	10	See cover ID chart	92-0460-3200	92-0460-3220
	1983 - 1996	FORD	8.8" rg	31	10		92-0688-3108	92-0688-3128
	1983 - 1985	DANA	Model 70	35	10			
	1980 - 1985	DANA	Model 61	30	10	Semi-floating axle		
	1980 - 1985	DANA	Model 60	30	10	Semi-floating axle	92-0460-3005	92-0460-3025
	1969 - 1979	DANA	Model 60	30	10	Semi-floating axle	92-0460-3000	92-0460-3020
Pick-Up (F250 Super-Duty)								
Rear Axle								
	1999 - 2000	FORD	10.5" rg	35	12	See cover ID chart (3 pinion)	92-0605-3500	92-0605-3520
	1985 - 2000	FORD	10.25" rg	35	12	See cover ID chart (2 pinion)		
Pick-Up (F350)								
Front Axle (see notice at end of page 4)								
	1974 - 1997	DANA	Model 60	35	10		92-0460-3500	92-0460-3520
	1980 - 1985	DANA	Model 50	30	10	Beam axle		
	1981	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1985 - 1998	FORD	10.25" rg	35	12	See cover ID chart (2 pinion)		
	1980 - 1985	DANA	Model 70	35	10			
	1980 - 1985	DANA	Model 60	30	10	Semi-floating axle	92-0460-3005	92-0460-3025
	1975 - 1981	DANA	Model 61	30	10			
	1974 - 1979	DANA	Model 60	30	10		92-0460-3000	92-0460-3020

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Pick-Up (F350 Super-Duty)								
Front Axle (see notice at end of page 4)								
	1998 - 2000	DANA	Model 60	35	10		92-0460-3500	92-0460-3520
Rear Axle								
	1999 - 2000	FORD	10.5" rg	35	10	See cover ID chart (3 pinion)	92-0605-3500	92-0605-3520
	1998 - 2000	DANA	Model 80	35	10			
Pick-Up (F450 Super-Duty)								
Front Axle (see notice at end of page 4)								
	1988 - 2000	DANA	Model 60	35	10		92-0460-3500	92-0460-3520
Rear Axle								
	1988 - 2000	DANA	Model 80	37	10			
Ranger								
Front Axle (see notice at end of page 4)								
	1997 - 2000	DANA	Model 35	27	10	IFS & ABS	92-0435-2702	
	1987 - 1997	DANA	Model 35	27	10	IFS	92-0435-2701	
	1983 - 1997	DANA	Model 28	23	12			
Rear Axle								
	1987 - 1994	FORD	8.8" rg	28	10	4.0/4.9 eng	92-0688-2807	92-0688-2827
	1983 - 2000	FORD	7.5" rg	28	10	2.5/2.9/3.0 eng		
	1984 - 1986	FORD	8.8" rg	31	10	4.0 engine	92-0688-3107	92-0688-3127
Vans (1/2-ton)								
Rear Axle								
	1997 - 2000	FORD	9.75" rg	34	10	5.4 eng		
	1987 - 2000	FORD	8.8" rg	31	10	w/ Removeable Carrier	92-0688-3108	92-0688-3128
	1965 - 1987	FORD	9" rg	31	10	w/ Non-Removeable Carrier	92-0690-3100	
Vans (3/4-ton)								
Rear Axle								
	1997 - 2000	FORD	9.75" rg	34	10			
	1980 - 2000	DANA	Model 60	30	10	Semi-floating axle	92-0460-3005	92-0460-3025
	1987 - 1996	FORD	8.8" rg	31	10	See cover ID chart	92-0688-3108	92-0688-3128
	1979 - 1987	DANA	Model 61	30	10	See cover ID chart		
	1983 - 1986	FORD	8.8" rg	31	10	See cover ID chart	92-0688-3107	92-0688-3127
	1968 - 1974	FORD	9" rg	31	10		92-0690-3100	
Vans (1-ton)								
Rear Axle								
	1997 - 2000	FORD	9.75" rg	34	10	See cover ID chart		
	1980 - 2000	DANA	Model 60	30	10	Semi-floating axle	92-0460-3005	92-0460-3025
	1975 - 2000	DANA	Model 70	35	10	See cover ID chart		
	1995 - 1996	DANA	Model 60	32	10		92-0460-3200	92-0460-3220
	1979 - 1987	DANA	Model 61	30	10	See cover ID chart		
	1968 - 1974	DANA	Model 60	35	10		92-0460-3500	92-0460-3520
Van (Super-Duty)								
Rear Axle								
	1996 - 2000	DANA	Model 80	37	10			

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

POWERTRAX No-Slip Traction System

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	GM Gov Lock	Dana Trac Lock
Jimmy (S15)									
Front Axle (see notice at end of page 4)									
	1991 - 2000	GM	7.2" rg	26					
Rear Axle									
	1995 - 2000	GM	8.5" rg	30	10	Z71 OPT/RPO G87	92-0785-3005		
	1988 - 2000	GM	7.625" rg	28	10	4WD V6	92-0776-2805	92-0776-2885	
	1983 - 1992	GM	7.5" rg	26	10	2WD All & 4WD 4 CYL	92-0775-2605		
Jimmy (Full size)									
Front Axle (see notice at end of page 4)									
	1994	GM	9.2" rg	33		IFS w/turbo diesel	92-0792-3301		
	1992 - 1994	GM	8.2" rg	28		IFS w/6 lug			
	1989 - 1991	GM	8.5" rg	30	10	Beam Axle	92-0785-3005		
	1979 - 1988	GM	8.5" rg	28	10	Beam Axle	92-0785-2805		
	1969 - 1980	DANA	Model 44	30	10	See cover ID chart	92-0444-3000		92-0444-3020
Rear Axle									
	1992 - 1994	GM	9.5" rg	33	14	All w/14 bolt cover	92-0795-3305		
	1989 - 1994	GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
	1982 - 1988	GM	8.5" rg	28	10		92-0785-2805		
	1969 - 1981	GM	8.875" rg	30	12		92-0788-3005		
Pick-Up (1/2-ton)									
Front Axle (see notice at end of page 4)									
	1988 - 2000	GM	9.2" rg	33		All w/turbo diesel	92-0792-3301		
	1988 - 2000	GM	8.2" rg	28		IFS 6 Lug			
	1978 - 1984	GM	8.5" rg	28	10	See cover ID chart	92-0785-2805		
	1963 - 1980	DANA	Model 44	30	10	See cover ID chart	92-0444-3000		92-0444-3020
Rear Axle									
	1988 - 2000	GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
	1988 - 2000	GM	9.5" rg	33	14	All w/14 bolt cover	92-0795-3305		
	1978 - 1988	GM	8.5" rg	28	10	See cover ID chart	92-0785-2805		
	1969 - 1981	GM	8.875" rg	30	12	All w/12 bolt cover	92-0788-3005		
	1969 - 1977	DANA	Model 44	30	10	See cover ID chart	92-0444-3000		92-0444-3020
	1968 - 1972	DANA	Model 44	30	10		92-0444-3000		92-0444-3020
Pick-Up (3/4-ton)									
Front Axle (see notice at end of page 4)									
	1989 - 2000	GM	9.2" rg	33	14	IFS w/8 lug	92-0792-3301		
	1988 - 2000	GM	8.2" rg	28	10	IFS w/6 lug			
	1989 - 1991	GM	8.5" rg	30	10	Beam Axle	92-0785-3005		
	1978 - 1988	GM	8.5" rg	28	10	VIN # R/V	92-0785-2805		
	1968 - 1980	DANA	Model 44	30		See cover ID chart	92-0444-3000		92-0444-3020
Rear Axle									
	1973 - 2000	GM	9.5" rg	33	14	Semi-floating axle	92-0795-3305		
	1973 - 2000	GM	10.5" rg	30	14	Full-floating Axle	92-0705-3000		
	1975 - 1977	DANA	Model 60	35	10	See cover ID chart	92-0460-3500		92-0460-3520
	1965 - 1974	DANA	Model 60	30	10	See cover ID chart	92-0460-3000		92-0460-3020

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	GM Gov Lock	Dana Trac Lock
Pick-Up (1-ton)									
Front Axle (see notice at end of page 4)									
	1988 - 2000	GM	9.2" rg	33		IFS w/VIN # C/K	92-0792-3301		
	1977 - 1991	DANA	Model 60	35	10	VIN # R/V	92-0460-3500		92-0460-3520
Rear Axle									
	1992 - 2000	DANA	Model 80	37	10	HD opt			
	1989 - 2000	GM	9.5" rg	33	14	Canada,SF Axle	92-0795-3305		
	1973 - 2000	GM	10.5" rg	30	14	w/14 bolt cover	92-0705-3000		
	1973 - 1991	DANA	Model 70	35	10	All w/10 bolt cover	Spring 2001		
S15									
Front Axle (see notice at end of page 4)									
	1991 - 2000	GM	7.2" rg	26					
Rear Axle									
	1995 - 2000	GM	8.5" rg	30	10	Z71 OPT/RPO G87	92-0785-3005		
	1988 - 2000	GM	7.625" rg	28	10	4WD V6	92-0776-2805	92-0776-2885	
	1983 - 1992	GM	7.5" rg	26	10	2WD All & 4WD 4 CYL	92-0775-2605		
Safari									
Front Axle (see notice at end of page 4)									
	1990 - 2000	GM	7.2" rg	26					
Rear Axle									
	1990 - 2000	GM	7.625" rg	28	10		92-0776-2805	92-0776-2885	
	1985 - 1989	GM	7.5" rg	26	10		92-0775-2605		
Sierra									
Front Axle (see notice at end of page 4)									
	1999 - 2000								
Rear Axle									
	1999 - 2000	GM	8.6" rg	30	10		92-0786-3005		
Sonoma									
Front Axle (see notice at end of page 4)									
	1991 - 2000	GM	7.2" rg	26					
Rear Axle									
	1995 - 2000	GM	8.5" rg	30	10	Z71 OPT/RPO G87	92-0785-3005		
	1988 - 2000	GM	7.625" rg	28	10	4WD V6	92-0776-2805	92-0776-2885	
	1983 - 1992	GM	7.5" rg	26	10	2WD All & 4WD 4 CYL	92-0775-2605		
Suburban (1/2-ton)									
Front Axle (see notice at end of page 4)									
	1992 - 1999	GM	8.2" rg	28		IFS w/o turbo die			
	1989 - 1991	GM	8.5" rg	30	10	Beam axle	92-0785-3005		
	1977 - 1988	GM	8.5" rg	28	10		92-0785-2805		
	1965 - 1980	DANA	Model 44	30	10		92-0444-3000		92-0444-3020
	1965 - 1968	DANA	Model 60	35	10	series only - Heavy D	92-0460-3500		92-0460-3520
Rear Axle									
	1992 - 2000	GM	9.5" rg	33	14	All w/14 bolt cover	92-0795-3305		
	2000	GM	8.6" rg	30	10	All w/10 bolt cover	92-0786-3005		
	1989 - 1999	GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
	1978 - 1988	GM	8.5" rg	28	10	All w/10 bolt cover	92-0785-2805		
	1965 - 1981	GM	8.875" rg	30	12	All w/12 bolt cover	92-0788-3005		
	1965 - 1972	DANA	Model 60	30	10		92-0460-3000		92-0460-3020
	1965 - 1968	DANA	Model 44	30	10		92-0444-3000		92-0444-3020

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	GM Gov Lock	Dana Trac Lock
Suburban (¾-ton)									
Front Axle (see notice at end of page 4)									
	1992 - 2000	GM	9.2" rg	33		IFS w/8 lug	92-0792-3301		
	1992 - 1999	GM	8.2" rg	28		IFS w/6 lug			
	1989 - 1991	GM	8.5" rg	30	10	Beam axle	92-0785-3005		
	1978 - 1988	GM	8.5" rg	28	10	Beam axle	92-0785-2805		
	1963 - 1980	DANA	Model 44	30	10	See cover ID chart	92-0444-3000		92-0444-3020
Rear Axle									
	2000	GM	8.6" rg	30	10		92-0786-3005		
	1981 - 1999	GM	9.5" rg	33	14	F Axle w/14 bolt cover	92-0795-3305		
	1973 - 1999	GM	10.5" rg	30	14	F Axle w/14 bolt cover	92-0705-3000		
	1989 - 1991	GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
	1977 - 1988	GM	8.5" rg	28	10	All w/10 bolt cover	92-0785-2805		
	1969 - 1980	DANA	Model 44	30	10	See cover ID chart	92-0444-3000		92-0444-3020
	1968 - 1980	DANA	Model 60	30	10	See cover ID chart	92-0460-3000		92-0460-3020
Vans (½-ton)									
Rear Axle									
	1999 - 2000								
	1989 - 1998	GM	8.5" rg	30	10	All	92-0785-3005		
	1979 - 1988	GM	8.5" rg	28	10	All	92-0785-2805		
	1965 - 1981	GM	8.875" rg	30	12	All w/12 bolt cover	92-0788-3005		
	1964 - 1971	GM	8.2" rg	28	10	All w/10 bolt cover	Spring 2001		
Vans (¾-ton)									
Rear Axle									
	1999 - 2000								
	1996 - 1998	GM	10.5" rg	30	14	F Axle, w/14 bolt cover	92-0705-3000		
	1996 - 1998	GM	9.5" rg	33	14	F Axle, w/14 bolt cover	92-0795-3305		
	1989 - 1996	GM	8.5" rg	30	10	All w/10 bolt cover	92-0785-3005		
	1979 - 1988	GM	8.5" rg	28	10	All w/10 bolt cover	92-0785-2805		
	1965 - 1981	GM	8.875" rg	30	12	All w/12 bolt cover	92-0788-3005		
Vans (1-ton)									
Rear Axle									
	1999 - 2000								
	1983 - 1998	GM	9.5" rg	33	14	F Axle, w/14 bolt cover	92-0795-3305		
	1973 - 1998	GM	10.5" rg	30	14	F Axle, w/14 bolt cover	92-0705-3000		
	1975 - 1991	DANA	Model 70	35	10	DRW 7500 gww	Spring 2001		
	1974 - 1991	DANA	Model 60	35	10	DRW 6200 gww	92-0460-3500		92-0460-3520
Yukon									
Front Axle (see notice at end of page 4)									
	1994 - 1999	GM	9.2" rg	33		IFS w/turbo diesel	92-0792-3301		
	1992 - 1999	GM	8.2" rg	28		IFS w/6 Lug			
Rear Axle									
	1992 - 1999	GM	8.5" rg	30	10		92-0785-3005		
Yukon XL - Suburban									
Front Axle (see notice at end of page 4)									
	2000	GM							
Rear Axle									
	2000	GM	8.6" rg	30	10		92-0786-3005		

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

HONDA

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Passport								
Rear Axle								
	1996 - 1999	GM	7.625" rg	28	10	4 cyl & 2WD	92-0776-2805	92-0776-2885
	1994 - 1998	DANA	Model 44	30	10	V6	92-0444-3000	92-0444-3020
	1994 - 1995	GM	7.5" rg	26	10	4 cyl & 2WD	92-0775-2605	92-0775-2685

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

IHC (International Harvester)

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Scout								
Front Axle (see notice at bottom of page)								
	1961 - 1971	DANA	Model 27	10	10			
Rear Axle								
	1967 - 1971	DANA	Model 44	19	10		92-0444-1900	
	1961 - 1967	DANA	Model 27	10	10			
Scout II								
Front Axle (see notice at bottom of page)								
	1972 - 1980	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1968 - 1980	DANA	Model 44	30	10		92-0444-3000	92-0444-3020

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

ISUZU

							POWERTRAX No-Slip Traction System		
Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	Open Differential	GM Gov Lock	Dana Trac Lock
Amigo									
Rear Axle									
	1998 - 2000	GM	7.625" rg	28	10	2WD	92-0776-2805	92-0776-2885	
	1998 - 2000	DANA	Model 44	30	10	4WD	92-0444-3000		92-0444-3020
Hombre									
Front Axle (see notice at bottom of page)									
	1996 - 1999	GM	7.2" rg	26					
Rear Axle									
	1996 - 1999	GM	7.625" rg	28	10	2WD	92-0776-2805	92-0776-2885	
P'up									
Rear Axle									
	1990 - 1994	GM	7.5" rg	26	10	2WD U.S. Built	92-0775-2605		
Rodeo									
Front Axle (see notice at bottom of page)									
	1998 - 2000	DANA	Model 44	30	10	IFS	92-0444-3001		
Rear Axle									
	1993 - 2000	DANA	Model 44	30	10		92-0444-3000		92-0444-3020
	1991 - 1992	ISUZU		26		4WD (Japan)			
	1991 - 2000	GM	7.625" rg	28	10	4cyl & 2WD	92-0776-2805	92-0776-2885	
Trooper									
Rear Axle									
	1984 - 1987	ISUZU		17					
	1988 - 1991	ISUZU		26					

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

JEEP

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Cherokee XJ								
Front Axle (see notice at bottom of page 3)								
	1984 - 2000	DANA	Model 30	27	10		92-0430-2700	
Rear Axle								
	1997 - 2000	CHRYSLER	8.25" rg	29	10		92-0382-2905	
	1994 - 1997	DANA	Model 35	27	10	Trac-Lok standard	92-0435-2706	92-0435-2725
	1991 - 1996	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2745
	1987 - 1993	DANA	Model 44	30	10	(metric ton or towin	92-0444-3000	92-0444-3020
	1990 - 1993	DANA	Model 35	27	10		92-0435-2705	92-0435-2725
	1984 - 1989	DANA	Model 35	27	10		92-0435-2700	92-0435-2720
CJ-2A								
Front Axle (see notice at bottom of page 3)								
	1945 - 1949	DANA	Model 25	10	10			
Rear Axle								
	1945 - 1949	DANA	Model 41	10	10			
CJ-3A								
Front Axle (see notice at bottom of page 3)								
	1948 - 1953	DANA	Model 25	10	10			
Rear Axle								
	1949 - 1953	DANA	Model 44	10	10			
	1948	DANA	Model 41	10	10			
CJ-3B								
Front Axle (see notice at bottom of page 3)								
	1964 - 1968	DANA	Model 27	10	10			
	1952 - 1964	DANA	Model 25	10	10			
Rear Axle								
	1966 - 1968	DANA	Model 44	19	10		92-0444-1900	
	1952 - 1965	DANA	Model 44	10	10			
CJ-5								
Front Axle (see notice at bottom of page 3)								
	1972 - 1983	DANA	Model 30	27	10		92-0430-2700	
	1966 - 1971	DANA	Model 27	10	10			
	1955 - 1965	DANA	Model 25	10	10			
Rear Axle								
	1976 - 1983	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920
	1971 - 1975	DANA	Model 44	30	10		92-0444-3000	
	1966 - 1970	DANA	Model 44	19	10	Thru mid 70	92-0444-1900	
	1955 - 1965	DANA	Model 44	10	10			

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
CJ-6								
Front Axle (see notice at bottom of page 3)								
	1972 - 1975	DANA	Model 30	27	10		92-0430-2700	
	1966 - 1971	DANA	Model 27	10	10			
	1958 - 1965	DANA	Model 25	10	10			
Rear Axle								
	1971 - 1975	DANA	Model 44	30	10		92-0444-3000	
	1966 - 1970	DANA	Model 44	19	10		92-0444-1900	
	1958 - 1965	DANA	Model 44	10	10			
CJ-7								
Front Axle (see notice at bottom of page 3)								
	1976 - 1986	DANA	Model 30	27	10		92-0430-2700	
Rear Axle								
	1976 - 1986	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920
CJ-8 Scrambler								
Front Axle (see notice at bottom of page 3)								
	1981 - 1985	DANA	Model 30	27	10		92-0430-2700	
Rear Axle								
	1981 - 1985	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920
Comanche								
Front Axle (see notice at bottom of page 3)								
	1986 - 1992	DANA	Model 30	27	10		92-0430-2700	
Rear Axle								
	1986 - 1992	DANA	Model 35	27	10		92-0435-2705	92-0435-2725
	1986 - 1992	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
	1986	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920
Grand Cherokee ZJ								
Front Axle (see notice at bottom of page 3)								
	1993 - 2000	DANA	Model 35	27	10	Select-Trac	92-0435-2706	
	1993 - 2000	DANA	Model 30	27	10	Command-Track	92-0430-2700	
	1980 - 1987	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1999 - 2000	DANA	Model 44	30	10	Special case		
	1993 - 2000	DANA	Model 35	27	10	See cover ID chart	92-0435-2706	
	1997 - 1998	CHRYSLER	8.25" rg	29	10		92-0382-2905	
	1995 - 1998	DANA	Model 44	30	10	See cover ID chart	92-0444-3000	92-0444-3020
	1993 - 1996	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2745
	1986 - 1987	DANA	Model 44	30	10	See cover ID chart	92-0444-3000	92-0444-3020
	1980 - 1986	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Wrangler TJ & YJ								
Front Axle (see notice at bottom of page 3)								
	1997 - 2000	DANA	Model 30	27	10		92-0430-2700	
Rear Axle								
	1997 - 2000	DANA	Model 44	30	10	Special case		
	1994 - 2000	DANA	Model 35	27	10		92-0435-2706	92-0435-2725
	1990 - 1993	DANA	Model 35	27	10		92-0435-2705	92-0435-2725
	1987 - 1989	DANA	Model 35	27	10		92-0435-2700	92-0435-2720

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

JEEP

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Grand Wagoneer								
Front Axle (see notice at bottom of page 2)								
	1993	DANA	Model 44	30		IFS	92-0444-3001	
	1984 - 1991	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1993	DANA	Model 35	27	10		92-0435-2705	92-0435-2725
	1986 - 1991	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
	1984 - 1986	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920
J Pick-Up								
Front Axle (see notice at bottom of page 2)								
	1962 - 1972	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1971 - 1972	DANA	Model 60	30	10		92-0460-3005	92-0460-3025
	1962 - 1970	DANA						
	1962 - 1968	DANA	Model 70	35	10	Dual Rear Wheel	Spring 2001	
J-10 Pick-up								
Front Axle (see notice at bottom of page 2)								
	1973 - 1988	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1973 - 1988	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
	1979 - 1986	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920
J-20 Pick-up								
Front Axle (see notice at bottom of page 2)								
	1973 - 1988	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1986 - 1988	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920
	1973 - 1988	DANA	Model 44	30	10	See cover ID chart	92-0444-3000	92-0444-3020
Jeepster Commando								
Front Axle (see notice at bottom of page 2)								
	1972 - 1973	DANA	Model 30	27	10		92-0430-2700	
	1967 - 1971	DANA	Model 27	10	10			
Rear Axle								
	1967 - 1973	DANA	Model 44	30	10		92-0444-3000	
	1967 - 1970	DANA	Model 30	27	10		92-0430-2700	
Pick-Up								
Front Axle (see notice at bottom of page 2)								
	1980 - 1987	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
Rear Axle								
	1995 - 2000	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
	1993 - 2000	DANA	Model 35	27	10		92-0435-2706	
	1997 - 1999	CHRYSLER	8.25" rg	29	10		92-0382-2905	
	1993 - 1996	CHRYSLER	8.25" rg	27	10		92-0382-2705	92-0382-2745
	1986 - 1987	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
	1980 - 1986	AMC	AMC 20	29	12		92-0120-2900	92-0120-2920

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Wagoneer SJ								
Front Axle (see notice at bottom of page 2)								
	1974 - 1991	DANA	Model 44	30	10		92-0444-3000	92-0444-3020
	1973	DANA	Model 30	27	10		92-0430-2700	
	1962 - 1972	DANA	Model 27	10	10			
Rear Axle								
	1971 - 1990	DANA	Model 44	30	10	See cover ID chart	92-0444-3000	92-0444-3020
	1984 - 1990	DANA	Model 35	27	10		92-0435-2705	92-0435-2725
	1962 - 1968	DANA	Model 44	19	10		92-0444-1900	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

LEXUS

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
LX-450								
Front Axle (see notice at bottom of page)								
	1996 - 2000	TOYOTA	8" rg	30			92-2080-3001	
Rear Axle								
	1996 - 2000	TOYOTA	8.875" rg	30	12		92-2088-3005	
LX-470								
Front Axle (see notice at bottom of page)								
	1999 - 2000							
Rear Axle								
	1999 - 2000							

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

LINCOLN

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Continental								
Rear Axle								
	1982 - 1987	FORD	7.5" rg	28	10	6 Cyl.		
	1982 - 1987	FORD	8.8" rg	28	10	8 Cyl	92-0688-2807	92-0688-2827
LS								
Rear Axle								
	2000							
Mark Series								
Rear Axle								
	1993 - 2000	FORD	7.5" rg	28	10			
	1980 - 1997	FORD	8.8" rg	28	10	4.0 engine or larger	92-0688-2807	92-0688-2827
	1984 - 1987	FORD	7.5" rg	28	10			
	1968 - 1979	FORD	9" rg	28	10		92-0690-2800	
Town Car								
Rear Axle								
	1980 - 2000	FORD	8.8" rg	28	10		92-0688-2807	92-0688-2827
	1966 - 1979	FORD	9" rg	28	10		92-0690-2800	
Navigator								
Front Axle (see notice at bottom of page)								
	1998 - 2000	DANA	Model 44	30		IFS	92-0444-3001	
Rear Axle								
	1998 - 2000	FORD	9.75" rg	34	10			

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

MAZDA

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Navajo								
Front Axle (see notice at bottom of page)								
	1991 - 1994	DANA	Model 28	23	12			
Rear Axle								
	1991 - 1994	FORD	8.8" rg	31	10		92-0688-3108	92-0688-3128
Pick-Up								
Front Axle (see notice at bottom of page)								
	1998 - 2000	DANA	Model 35	27	10		92-0435-2701	
	1991 - 1994	DANA	Model 28	23	12			
Rear Axle								
	1994 - 2000	FORD	8.8" rg	31	10	4.0 V6	92-0688-3108	92-0688-3128
	1994 - 2000	FORD	7.5" rg	28	10	3.0 V6		

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

MERCURY

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Bobcat								
Rear Axle								
	1975 - 1980	FORD	8" rg	28	10	6 Cyl	92-0680-2800	
	1975 - 1980	FORD	6.75" rg			4 Cyl		
Capri								
Rear Axle								
	1986	FORD	8.8" rg	28	10	V8	92-0688-2807	92-0688-2827
	1979 - 1986	FORD	7.5" rg	28	10	6 Cyl		
	1979 - 1982	FORD	6.75" rg					
	1970 - 1978	FORD						
Comet								
Rear Axle								
	1964 - 1977	FORD	8" rg	28	10	302 or smaller eng.	92-0680-2800	
	1966 - 1969	FORD	9" rg	28	10	'8-351W/390/427/428	92-0690-2800	
	1964 - 1968	FORD	7.25" rg	28	8	6 Cyl		
Cougar								
Rear Axle								
	1988 - 1998	FORD	8.8" rg	31	10	3T, after market axle	92-0688-3107	92-0688-3127
	1986 - 1997	FORD	8.8" rg	28	10	All V8	92-0688-2807	92-0688-2827
	1979 - 1997	FORD	7.5" rg	28	10	All V6		
	1979 - 1982	FORD	7.25" rg	28	8	4 Cyl		
	1969 - 1979	FORD	9" rg	28	10	V8-390/427/428	92-0690-2800	
	1969 - 1979	FORD	9" rg	31	10	after market axle	92-0690-3100	
	1967 - 1978	FORD	8" rg	28	10	V8 289/302	92-0680-2800	
Marquis								
Rear Axle								
	1986	FORD	7.5" rg	28	10	V6		
Monarch								
Rear Axle								
	1975 - 1980	FORD	8" rg	28	10		92-0680-2800	
	1975 - 1980	FORD	9" rg	28	10	V8-351W/400/460	92-0690-2800	
	1975 - 1976	FORD	8.75" rg	28	10	V8-351W/400/460	92-0690-2800	
Montego								
Rear Axle								
	1970 - 1976	FORD	9" rg	28	10	V8-351W/400/460	92-0690-2800	
	1970 - 1974	FORD	8" rg	28	10	V8-351M	92-0680-2800	
Versailles								
Rear Axle								
	1977 - 1980	FORD	9" rg	28	10		92-0690-2800	

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Zephyr								
Rear Axle								
	1978 - 1983	FORD	7.5" rg	28	10	6 Cyl.		
	1979 - 1982	FORD	6.75" rg			4 Cyl		
Front Axle (see notice at end of page 2)								
	1997 - 2000	DANA	Model 35	27	10		92-0435-2701	
Rear Axle								
	1997 - 2000	FORD	8.8" rg	31	10		92-0688-3108	92-0688-3128
Mountaineer								
Front Axle (see notice at end of page 2)								
	1997 - 2000		DANA	Model 35	27	10	92-0435-2701	
Rear Axle								
	1997 - 2000		FORD	8.8" rg	31	10	92-0688-3108	92-0688-3128

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

OLDSMOBILE

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Gov Lock
Cutlass								
Rear Axle								
	1985 - 1988	GM	8.5" rg	28	10	V8	92-0785-2805	
	1978 - 1988	GM	7.5" rg	26	10		92-0775-2605	
	1977	GM	8.875" rg	30	12	V8-396 Eng. Or larger	92-0788-3005	
	1973 - 1977	GM	8.5" rg	28	10		92-0785-2805	
	1973 - 1976	GM	8.875" rg	31		Station Wagon		
	1961 - 1970	GM	8.2" rg	28	10		Spring 2001	
F-85								
Rear Axle								
	1971 - 1972	GM	8.5" rg	28	10		92-0785-2805	
	1969	GM	8.875" rg	30	12		92-0788-3005	
	1967 - 1969	GM	8.2" rg	28	10		Spring 2001	
Starfire								
Rear Axle								
	1975 - 1980	GM	7.5" rg	26	10		92-0775-2605	
	1976 - 1977	GM	6.5" rg					
Sunbird								
Rear Axle								
	1976 - 1980	GM	7.5" rg	26	10		92-0775-2605	
	1976 - 1977	GM	6.5" rg					
Bravado								
Front Axle (see notice at bottom of page)								
	1991 - 2000	GM	7.2" rg	26				
Rear Axle								
	1995 - 2000	GM	8.5" rg	30	10	Z71 OPT/RPO G87	92-0785-3005	
	1991 - 2000	GM	7.625" rg	28	10	4WD V6	92-0776-2805	92-0776-2885

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.

PLYMOUTH

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Barracuda								
Rear Axle								
	1968 - 1974	CHRYSLER	8.75" rg	30	10	All W/Removable carrier		
	1970 - 1971	DANA	Model 60	30	10	V8-426/440	92-0460-3000	92-0460-3020
	1964 - 1971	CHRYSLER	7.25" rg	25	9			
Prowler								
Rear Axle								
	1997 - 2000	DANA	Model 44	30				
Valiant								
Rear Axle								
	1973 - 1976	CHRYSLER	8.25" rg	27	10	V8-318	92-0382-2705	92-0382-2725
	1962 - 1976	CHRYSLER	7.25" rg	25	9	6 Cyl		
	1966 - 1972	CHRYSLER	8.75" rg	30	10	V8-360		
Volare								
Rear Axle								
	1976 - 1980	CHRYSLER	8.25" rg	27	10	V8	92-0382-2705	92-0382-2725
	1976 - 1980	CHRYSLER	7.25" rg	25	9	6 Cyl		

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

PONTIAC

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Astre								
Rear Axle								
	1976 - 1977	GM	6.5" rg					
	1975 - 1977	GM	7.5" rg	26	10		92-0775-2605	
Firebird								
Rear Axle								
	1993 - 2000	ZEXEL				Z28/Y87		
	1990 - 2000	GM	7.625" rg	28	10	V6 manual trans	92-0776-2805	
	1987 - 1989	GM	7.75" rg		9	V8 w/o Z87		
	1982 - 1984	GM	7.5" rg	26	10	4 cyl/V6 auto	92-0775-2605	
	1971 - 1981	GM	8.5" rg	28	10	All	92-0785-2805	
	1967 - 1970	GM	8.2" rg	28	10	6 cyl	Spring 2001	
	1967 - 1970	GM	8.875" rg	30	12	V8	92-0788-3005	
Grand Prix								
Rear Axle								
	1978	GM	7.5" rg	26	10		92-0775-2605	
	1973 - 1977	GM	8.5" rg	28	10		92-0785-2805	
	1973 - 1976	GM	8.875" rg	31		Station Wagon		
	1969 - 1972	GM	8.2" rg	28	10		Spring 2001	
	1969 - 1970	GM	8.875" rg	30	12		92-0788-3005	
LeMans								
Rear Axle								
	1978 - 1981	GM	7.5" rg	26	10		92-0775-2605	
	1977	GM	8.875" rg	30	12		92-0788-3005	
	1973 - 1977	GM	8.5" rg	28	10		92-0785-2805	
	1973 - 1976	GM	8.875" rg	31		Station Wagon		
Phoenix								
Rear Axle								
	1977 - 1979	GM	8.5" rg	28	10		92-0785-2805	
	1977 - 1979	GM	7.5" rg	26	10		92-0775-2605	
Tempest								
Rear Axle								
	1970 - 1972	GM	8.875" rg	30	12		92-0788-3005	
	1964 - 1969	GM	8.2" rg	28	10		Spring 2001	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

TOYOTA

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
4Runner								
Front Axle (see notice at end of page 2)								
	1986 - 2000	TOYOTA	7.5" rg	27		All		
	1984 - 1985	TOYOTA	8" rg	30		All	92-2080-3001	
Rear Axle								
	1986 - 2000	TOYOTA	8" rg	30		V6		
	1984 - 1989	TOYOTA	8" rg	30		except V6	92-2080-3001	
Land Cruiser								
Front Axle (see notice at end of page 2)								
	1998 - 2000	TOYOTA	9.5" rg					
	1990 - 1997	TOYOTA	8" rg	30			92-2080-3001	
	1969 - 1989	TOYOTA	8.875" rg	30	12		92-2088-3001	
	1950 - 1968	TOYOTA	8.875" rg	10			92-2088-1005	
Rear Axle								
	1998 - 2000	TOYOTA						
	1969 - 1997	TOYOTA	8.875" rg	30	12		92-2088-3005	
	1950 - 1968	TOYOTA	8.875" rg	10			92-2088-1005	
Pick-Up								
Front Axle (see notice at end of page 2)								
	1986 - 1995	TOYOTA	7.5" rg	27		IFS		
	1979 - 1985	TOYOTA	8" rg	30		Beam axle	92-2080-3001	
Rear Axle								
	1985 - 1995	TOYOTA	8" rg	30		w/ V6 or Turbo 4 cyl		
	1969 - 1995	TOYOTA	7.5" rg	27		All 2WD , 4 cyl.		
	1969 - 1995	TOYOTA	8" rg	30		All 4WD, 4 cyl	92-2080-3001	
T-100								
Front Axle (see notice at end of page 2)								
	1993 - 1998	TOYOTA	7.5" rg	27				
Rear Axle								
	1993 - 1998	TOYOTA	8" rg	30			92-2080-3002	
Tacoma 4X2								
Rear Axle								
	2000	TOYOTA				4 cyl		
	1995 - 1999	TOYOTA	7.5" rg	27		4 cyl		
	1995 - 1999	TOYOTA	8" rg	30		V6		
Tacoma 4X4								
Front Axle (see notice at end of page 2)								
	2000	TOYOTA				All		
	1995 - 1999	TOYOTA	7.5" rg	27		All		
Rear Axle								
	2000	TOYOTA				All		
	1995 - 1999	TOYOTA	8" rg	30		All	92-2080-3002	

Vehicle Make	Year Range	Manufacturer of Axle	Axle Model	Spline Count	Cover Bolts	Special Notes	POWERTRAX No-Slip Traction System	
							Open	Limited-Slip
Tundra								
Front Axle (see notice at end of page 2)								
2000								
Rear Axle								
1999 - 2000 TOYOTA 8" rg 30							92-2080-3002	

NOTICE REGARDING ACCURACY OF THIS GUIDE:

Powertrax has attempted to make this Application Guide as accurate as possible. However, Powertrax cannot guarantee correctness. Identical model vehicles may have different axles or differentials than stated in this guide depending on original options ordered and other factors. It is advisable to check the vehicle to determine precisely which differential and axle are present. **IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CONTACT US AT 800-578-1020.**

NOTICE REGARDING FRONT AXLE APPLICATIONS:

The Powertrax No-Slip Traction System works well on the front axle of 4-wheel drive vehicles provided a couple of important guidelines are followed. The Powertrax No-Slip Traction System should be used only on vehicles equipped with locking hubs on the front axle or with front axle disconnect. In addition, the vehicle must not be equipped with full time 4-wheel drive. Vehicles equipped with a Powertrax No-Slip Traction System on the front axle should not be operated on the highway with the front hubs locked and 4-wheel drive engaged. Following these guidelines will ensure very on-road driveability while still providing maximum off-road traction.